



Note: The resistors R19 and R26 on the motherboard are replaced with capacitors 47nF



SWR Tandem Match



2 провода 0.9мм пропущено через бинюкль
по диагонали пропущено и намотано по 10 витков 0.5мм

Title		
Size	Number	Revision
A4		
Date:	06-Dec-20	Sheet of
File:	C:\Tisho\AD8307 Add on v3.SchDoc	Drawn By:

Comment	Description	Designator	Footprint	LibRef	Quantity
PartNumber	CAP, CERM, +/- 10%, X7S, 0805, RES, 1%, 0.1 W, 0805	C1, C2, C3, C4, C5, C6, C7, C8, C9, C10, R1, R3, R5	0805_HV	C0805, R0805	13
PartNumber	RES, 1%, 0.5 W, 1206	R2, R4	1206	R1206	2
L78L05ACUTR		U1	STMicroelectronics _SOT-89-7098166_MFG	L78L05ACUTR	1
AD8307ARZ	Low Cost, DC to 500	U2, U3	ADI-R-8_M	AD8307ARZ	2